







R-1231 C



- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
 DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
 IRON AT MODERATE TEMPERATURE





R- 1231 B



- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
 DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
 IRON AT MODERATE TEMPERATURE









R-1231 A



- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
 DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
 IRON AT MODERATE TEMPERATURE









R-1231 D



- DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
 DO NOT OVER EXPOSE DAMP FABRIC TO STRONG SUNLIGHT
 IRON AT MODERATE TEMPERATURE